

Technical Service Bulletin (TSB)
Flash: Hybrid Control Processor (HCP) and
Auxiliary Hybrid Control Processor (AHCP) Updates

REFERENCE:	TSB: 08-003-25 GROUP: 08 - Electrical	Date:	January 8, 2025	REVISION:	08-231-24 REV. A
VEHICLES AFFECTED:	2024 (WL) Jeep Grand Cherokee / Grand Cherokee L This bulletin applies to vehicles built on and before August 14, 2024 (MDH 0814XX) equipped with a 2.0L I4 DOHC DI Turbo PHEV Engine (Sales Code ECX) and a 8-SPD Auto 8P75PH PHEV Transmission (Sales Code DFY) .			MARKET APPLICABILITY:	
				<input checked="" type="checkbox"/> NA	<input checked="" type="checkbox"/> MEA
				<input checked="" type="checkbox"/> SA	<input checked="" type="checkbox"/> IAP
				<input checked="" type="checkbox"/> EE	<input checked="" type="checkbox"/> CH
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs) : <ul style="list-style-type: none"> • P0C19 - Drive Motor A Torque Delivered Performance. • P1B03 - Resolver Signal / MCPA Rationality. • B273C - Digital Crash Input. Customers may experience the following: <ul style="list-style-type: none"> • Intermittent wrench (service HV) icon condition. 				
CAUSE:	HCP/AHCP module software updates				

This bulletin supersedes Technical Service Bulletin (TSB) 08-231-24 REV. A, date of issue November 09, 2024, which should be removed from your files. All revisions are highlighted with **asterisks**** and includes converting this to an information only bulletin.**

DISCUSSION:

NOTE: **The software required to perform this TSB is not available at this time.******

POLICY:

****Information Only****

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.