



SSM 53291 2025 Explorer - 2.3L EcoBoost - Turbocharger Removal Procedure Update

Some 2025 Explorer vehicles equipped with a 2.3L EcoBoost engine may require removal of the turbocharger due to various concerns. Workshop Manual, Section 303-04D has been updated with improved turbocharger removal and installation service procedure steps.