



Bulletin No.: PIT6313

Published date: 01/6/2025

Preliminary Information

PIT6313 Diagnostic Tip for the Name/Title Of DTCs U1616 / U1615 and/or U053B On Vehicles WithOUT Super Cruise

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All	All	All
Cadillac	CT5	2025	All	All	All
Cadillac	Escalade	2025	All	All	All
Cadillac	Escalade ESV	2025	All	All	All
Cadillac	Lyriq	2023 - 2025	All	All	All
Cadillac	XT4	2024 - 2025	All	All	All
Chevrolet	Blazer EV	2024 - 2025	All	All	All
Chevrolet	Equinox EV	2024 - 2025	All	All	All
Chevrolet	Silverado EV	2024 - 2025	All	All	All
Chevrolet	Suburban	2025	All	All	All
Chevrolet	Tahoe	2025	All	All	All
Chevrolet	Traverse	2024 - 2025	All	All	All
GMC	Acadia	2024 - 2025	All	All	All
GMC	Sierra EV	2024 - 2025	All	All	All
GMC	Yukon	2025	All	All	All
GMC	Yukon XL	2025	All	All	All


Involved Region or Country	North America
Additional Options (RPO)	With RPO UGN but withOUT RPO UKL Supercruise
Condition	When scanning a non-supercruise vehicle for DTCs, there may be some confusion with the name/title of DTCs U1615, U1616, and/or U053B. The naming of these DTC's may indicate they apply to the K124 Image Processor Module 1 - Processor 1, but vehicles without super cruise are not equipped with an Image Processor Module.
Cause	The naming of DTCs U1615, U1616, and / or U053B on vehicles without supercruise.

Correction:

When working on a non-supercruise vehicle with DTC's U1615, U1616, and/or U053B the wording "Image Processing Module 1 - Processor 1" should be replaced with the "B174W Front View Camera - Windshield".

Version History

Version	1
Modified	01/06/2025 - Created on.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.