



Bulletin No.: PIT6274B

Published date: 01/8/2025

Preliminary Information

PIT6274B Interior Vision Camera System With DTC B1C48 B1C46 B020A

Proactive

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All All	All	All
Cadillac	LYRIQ	2025	All All	All	All
Chevrolet	Blazer	2025	All All	All	All
Chevrolet	Blazer EV	2025	All All	All	All
Chevrolet	Equinox	2025	All All	All	All
Chevrolet	Equinox EV	2025	All All	All	All
Chevrolet	Silverado EV	2025	All All	All	All
Chevrolet	Suburban	2025	All All	All	All
Chevrolet	Tahoe	2025	All All	All	All
Chevrolet	Traverse	2025	All All	All	All
GMC	Sierra EV	2025	All All	All	All
GMC	Terrain	2025	All All	All	All
GMC	Yukon	2025	All All	All	All
GMC	Yukon XL	2025	All All	All	All

Involved Region or Country	United States, Canada, Mexico and Europe
Additional Options (RPO)	UCV - Connected Cameras Non-Equipped
Condition	A customer may comment about a possible intermittent Service Camera System Message and upon diagnostics, any of the following DTCs may be set as current or history. B020A, B1C64 or B1C48
Cause	This is a false DTC and/or message due to a software anomaly.

Correction:

Do not replace any parts at this time.

Engineering is aware of the concern.

The PI will be updated when a repair is available.

Until a fix is available, the concern can not be corrected by clearing codes.

Version History

Version	3
Modified	11/04/2024 - Created on. 12/05/2024 - Updated Labor Operation. 01/08/2025 - Updated Models, Condition, RPO box, Labor and Cause.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.