



Bulletin No.: PIT6185A
Published date: 01/13/2025

Preliminary Information

PIT6185A Forward Collision Alert / Automatic Emergency Braking (AEB) / Front Pedestrian Alert Inoperative with Forward Collision Icon Lamp On and No DTCs Present

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado 2500HD	2024	All	All	All
Chevrolet	Silverado 3500HD	2024	All	All	All
GMC	Sierra 2500HD	2024	All	All	All
GMC	Sierra 3500HD	2024	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	KGU (Universal Vehicle Module) & VYU (Snow Plow Prep / Camper Package)
Condition	Some customers may comment that Forward Collision Alert, Automatic Emergency Braking, and Front Pedestrian Alert are inoperative and the AEB forward collision icon lamp is illuminated in the cluster. No DTCs will be present and Lane Departure Warning, Adaptive Cruise, and Auto High Beam Assist (Intellibeam) will all be functional.
Cause	The cause of the condition is a software anomaly.

Correction:

Reprogram the Frontview Camera Module.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810835	Front View Camera Reprogramming with SPS	Use published time

Version History

Version	2
Modified	06/11/2024 - Created on. 01/13/2025 - Updated Correction