



Bulletin No.: PIC6539A
Published date: 01/15/2025

Preliminary Information

PIC6539A Heated Steering Wheel Inoperative During Remote Start

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Encore GX	2024 - 2025	All All	All	All
Buick	Envista	2024 - 2025	All All	All	All
Chevrolet	Trailblazer	2024 - 2025	All All	All	All
Chevrolet	Trax	2024 - 2025	All All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UVD
Condition	Customer may state that the heated steering wheel is inoperative when remote starting their vehicle.
Cause	This is normal operation.

Correction:

No repair attempts should be made to correct this condition. The heated steering wheel is a standalone module and does not communicate on any CAN buses and only works when commanded on by operator using its switch.

Version History

Version	2
Modified	02/14/2024 - Created on. 01/15/2025 - Updated Model years and RPO.