



**Bulletin No.:** PIC6564B

**Published date:** 01/10/2025

## Preliminary Information

### PIC6564B Diagnostic Tip: For Adding Trailer Lighting Or Trailer Lights Inoperative For Vehicles Built Without RPO: V92

#### Models

|               |               |                     |                        |                |                       |
|---------------|---------------|---------------------|------------------------|----------------|-----------------------|
| <b>Brand:</b> | <b>Model:</b> | <b>Model Years:</b> | <b>VIN:</b><br>from to | <b>Engine:</b> | <b>Transmissions:</b> |
| Cadillac XT4  |               | 2024 - 2025         | All All                | All            | All                   |

|                                   |   |
|-----------------------------------|---|
| <b>Involved Region or Country</b> | North America   |
| <b>Addition options (RPO)</b>     | Without V92 (TRAILER PROVISIONS) V08 (HEAVY DUTY COOLING SYSTEM)  |
| <b>Condition</b>                  | Customers may inquire about adding a trailer hitch and/or trailer lighting or a technician may find that the trailer lighting is inoperative. |
| <b>Cause</b>                      | Calibrations for trailer lighting are only available for vehicles with RPO V92  |

#### Correction:

As an expense to the customer, the dealer will need to contact Techline and request the VIN be reconfigured to include RPO's V92 and VR2.

Once the VIN has been reconfigured, the dealer will then need to reprogram the Lighting control module and the Park Assist control module to update the software that already includes these calibrations for V92.

Dealers will need to follow programming instructions per Service Information for the Lighting and Park assist modules.

#### Version History

|                 |  |
|-----------------|--|
| <b>Version</b>  | 3  |
| <b>Modified</b> | 07/30/2024 - Created on.<br>11/04/2024 - Updated Correction.<br>01/10/2025 - Updated Correction. |