



SSM 53319 2025 F-150 - Non-Lightning - DTC U3000:42 Setting In The ACM When A Diagnostic Self-Test Is Performed

Some 2025 F-150 non-Lightning vehicles may set diagnostic trouble code (DTC) U3000:42 in the audio control module (ACM) when a diagnostic self-test is performed. If DTC U3000:42 is present in the history status, it has no effect on functionality or durability of vehicle and can be cleared. Replacement or reprogramming of the ACM will not resolve this condition. Disregard DTC U3000:42 if no other DTCs are present in the ACM, no warning indicators are illuminated while the vehicle is on, and no additional symptoms are present. If other DTCs or observable symptoms are present, refer to Section 415-00 of Workshop Manual (WSM) for additional diagnosis and testing.