



## **SSM 53327 2020-2024 Transit - Lack Of Power Steering Assist At Engine Start-Up With DTC U3000:49 Stored In The PSCM - Built On 01-Aug-2019 And Through 23-Oct-2024**

Some 2020-2024 Transit vehicles built on 01-Aug-2019 and through 23-Oct-2024 may exhibit a lack of power steering assist on initial engine start-up with diagnostic trouble code (DTC) U3000:49 stored in the power steering control module (PSCM). This may be due to the PSCM software. Using the latest software version of the Ford Diagnosis and Repair System (FDRS) scan tool, reprogram the PSCM. If the concern is still present, refer to normal diagnostics in Workshop Manual, Section 211-02. For claiming, use causal part 3504 and applicable labor operations in Sections 03 and 10 of the Service Labor Time Standards (SLTS) Manual.