


Fault Code 3058/9

DD13 GEN 5 Engines



Description

- DD13 GEN 5 engines operated at high altitude (baro under 13 psi) are occasionally setting 3058/9 (EGR slow response.)
- It appears to align directly with the MY24 software release.
- **Factory Resolution**
 - 11/19/24 – Engineering is analyzing high altitude testing from our function trucks to better understand the issue.
 - 11/25/24 – Unit identified in the field for data logger. Data logger has been requested and is being built.
 - This will likely need a calibration update to correct.
- **Field Resolution**
 - No resolution at this time. Release the truck until a cal update is available. This fault code does result in a 25% derate.