

DTNA Solutions > Service Solutions > FCCC
> SS 285 FCCC eB2 (Jouley) and MT50e Telemetry Modul...

SS 285 FCCC eB2 (Jouley) and MT50e Telemetry Module Commissioning and Operation

Applicable Vehicles

FCCC eB2 and MT50e

Symptoms

Units can exhibit higher than normal parasitic drain on low voltage batteries if the telemetry module isn't commissioned correctly to receive regular software updates.

Failure to correctly commission the telemetry module can also impede ability to receive diagnostic data on operation of units in the field.

Issue

Some unit have incorrect SIM number and module number on telemetry module recorded.

Solution

Verify operation of the telemetry module. See figure 1.

Remove telemetry module to gain access to SIM number and model number labels and record information. Re-install module and submit recorded and customer information to FCCC through CAC ticket for commissioning verification. File warranty to PFP 66-18896-000 0.5 labor hrs.

Labels :

Busses

Step Vans

Add tags

Attachments



Comment

