

 Technical Service Bulletin	GROUP BODY	NUMBER 25-BD-001G
	DATE JANUARY 2025	MODEL(S) SEE BELOW
SUBJECT: DARK CHROME TRIM STAINED OR DISCOLORED		

This TSB supersedes 22-BD-008G to remove the cleaning procedure and revise the entire bulletin to replace the affected stained dark chrome trim.

Description: This procedure provides repair information for the dark chrome trim when stains are present. Some stains may occur from hard water or cleaning chemicals used during a car wash. Follow the procedures below to replace the affected dark chrome moldings.



Applicable Vehicles (Certain):

- 2019MY and later G70 (IK) vehicles
- 2017-2020MY G80 (DH) vehicles
- 2021MY and later G80 (RG3) vehicles
- 2022MY and later GV70 (JK1) vehicles
- 2021MY and later GV80 (JX1) vehicles

Parts Information:

Model	Part Name	Part Number
G70 (IK)	Moulding Assy-Frt Dr Frame, LH	82850-G9010
	Moulding Assy-Frt Dr Frame, RH	82860-G9010
	Moulding Assy-Rr Dr Frame, LH	83850-G9011
	Moulding Assy-Rr Dr Frame, RH	83860-G9011
	W/Strip Assy-Fr Dr Belt O/S, LH	82210-G9010
	W/Strip Assy-Fr Dr Belt O/S, RH	82220-G9010
	W/Strip Assy-Rr Dr Belt O/S, LH	83210-G9010
	W/Strip Assy-Rr Dr Belt O/S, RH	83220-G9010
	Grille Assy-Radiator	86350-G9EI0
		86350-G9FG0
G80 (DH)	Moulding Assy-Frt Dr Frame,LH	82850-B1600
	Moulding Assy-Frt Dr Frame,RH	82860-B1600
	Moulding Assy-Rr Dr Frame,LH	83850-B1600
	Moulding Assy-Rr Dr Frame,RH	83860-B1600
	W/Strip Assy-Fr Dr Belt O/S, LH	82210-B1600
	W/Strip Assy-Fr Dr Belt O/S, RH	82220-B1600
	W/Strip Assy-Rr Dr Belt O/S, LH	83210-B1600
	W/Strip Assy-Rr Dr Belt O/S, RH	83220-B1600
	Glass & Moulding Assy-Quarter Fixed,LH	87810-B1200
	Glass & Moulding Assy-Quarter Fixed,RH	87820-B1200
	Grille Assy-Radiator	86350-B1920

SUBJECT:**DARK CHROME TRIM STAINED OR DISCOLORED**

Model	Part Name	Part Number
G80 (RG3)	Moulding Assy-Frt Dr Frame, LH	82850-T1500
	Moulding Assy-Frt Dr Frame, RH	82860-T1500
	Moulding Assy-Rr Dr Frame, LH	83850-T1500
	Moulding Assy-Rr Dr Frame, RH	83860-T1500
	W/Strip Assy-Fr Dr Belt O/S, LH	82210-T1500
	W/Strip Assy-Fr Dr Belt O/S RH	82220-T1500
	W/Strip Assy-Rr Dr Belt O/S, LH	83210-T1500
	W/Strip Assy-Rr Dr Belt O/S, RH	83220-T1500
	Glass & Moulding Assy-Quarter Fixed, LH	87810-T1050
		87810-T1051
	Glass & Moulding Assy-Quarter Fixed, RH	87820-T1050
		87820-T1051
	Grille Assy-Radiator	86350-T1560
		86350-T1560
GV70 (JK1)	Moulding Assy-Frt Dr Frame, LH	86350-T1570
	Moulding Assy-Frt Dr Frame, RH	82860-AR010
	Moulding Assy-Rr Dr Frame, LH	83850-AR010
	Moulding Assy-Rr Dr Frame, RH	83860-AR010
	W/Strip Assy-Fr Dr Belt O/S, LH	82210-AR010
	W/Strip Assy-Fr Dr Belt O/S, RH	82220-AR010
	W/Strip Assy-Rr Dr Belt O/S, LH	83210-AR010
	W/Strip Assy-Rr Dr Belt O/S, RH	83220-AR010
	Glass & Moulding Assy-Quarter Fixed, LH	87810-AR100
		87810-AR500
	Glass & Moulding Assy-Quarter Fixed, RH	87820-AR100
		87820-AR500
	Grille Assy-Radiator	86350-AR700
		86350-AR710

SUBJECT:

DARK CHROME TRIM STAINED OR DISCOLORED

Model	Part Name	Part Number
GV80 (JX1)	Moulding Assy-Frt Dr Frame, LH	82850-T6020
	Moulding Assy-Frt Dr Frame, RH	82860-T6020
	Moulding Assy-Rr Dr Frame, LH	83850-T6020
	Moulding Assy-Rr Dr Frame, RH	83860-T6020
	W/Strip Assy-Fr Dr Belt O/S, LH	82210-T6200
	W/Strip Assy-Fr Dr Belt O/S, RH	82220-T6200
	W/Strip Assy-Rr Dr Belt O/S, LH	83210-T6200
	W/Strip Assy-Rr Dr Belt O/S, RH	83220-T6200
	Glass & Moulding Assy-Quarter Fixed, LH	878E0-T6700
	Glass & Moulding Assy-Quarter Fixed, RH	87820-T6700
	Grille Assy-Radiator	86351-T6000

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
ALL	Refer to WEBLTS	Refer to WEBLTS	Refer to WEBLTS	Refer to parts information above	A41	ZZ6

NOTE 1: Normal warranty applies.

NOTE 2: Submit claim on Claim Entry Screen as “Warranty” type.

NOTE 3: Take a picture of the warrantable defect. Op times include VIN, Mileage, and Repair validation photo(s) as outlined in the Digital Documentation Policy.

NOTE 4: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**


NOTE 5: If a part is found in need of replacement while performing this TSB and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

Service Procedure:

STUI

This TSB includes Repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

1. Inspect all exterior chrome surfaces on the vehicle to confirm which trim pieces have stains.



- 2.

STUI

Using STUI, take photos of each stained/discolored dark chrome trim with the last 6 digits of the VIN and the date of repair on a piece of paper.

Upload the photos to STUI.



3. Replace each affected dark chrome trim.

Refer to the applicable shop manual procedure for each part.
4. The service procedure is now complete.