



Bulletin No.: PIC5320C

Published date: 01/31/2025

Preliminary Information

PIC5320C Adding Radio Steering Wheel Control Switch (RPO NZL)

Models

| Brand: | Model: | Model Years: | VIN: from to | Engine: | Transmissions: |
|---------------|---------------|---------------------|-------------------------|----------------|-----------------------|
| Chevrolet | Camaro | 2010 - 2015 | All All | All | All |

Supersession Statement

This PI was superseded to update model years. Please discard all copies of PIC5320B. The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern


A customer may inquire if it is possible to install steering wheel mounted audio controls on a vehicle that was not originally built with that option.

Recommendations / Instructions

It is possible to install audio Steering Wheel Controls (SWC) on a vehicle that was not originally built with this option.

This modification will require installation of the appropriate right hand steering wheel control switch, the steering wheel pad accessory harness, and a re-calibration of the BCM. After the components have been installed on the vehicle, the dealership tech will need to contact the Techline Customer Support Center (TCSC) for a VCI number to recalibrate the BCM. TCSC will charge a fee for this service. It is up to the dealership to contact TCSC to find out what the current cost is for this calibration is so they can inform the customer before taking on this job.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.