



**Bulletin No.:** PIT6322

**Published date:** 01/21/2025

## Preliminary Information

### PIT6322 Turn Signal Flashes Fast or is Inoperative Intermittently

#### Product Investigation Review Required

#### Models

**Brand:** Chevrolet **Model:** Blazer EV **Model Years:** 2024 - 2025 **VIN:** All **from to:** All All **Engine:** All **Transmissions:** All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	Turn signal flashing fast or inoperative. The customer may state that the turn signal was inoperative and after cycling the ignition the turn signal works again. Possible message to check bulb.
<b>Cause</b>	Hardware

#### Correction:

Do not attempt any repairs at this time.

Advise the customer that engineering is working on an improved design to resolve this concern.

Advise the customer to continue to drive the vehicle while engineering works on a design improvement.

If the turn signal is completely inoperative and not intermittent follow SI diagnostics.

A bulletin will be released when a design improvement is available.

#### Version History

<b>Version</b>	1
<b>Modified</b>	01/21/2025 - Created on.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.