



**Bulletin No.:** PIP6038

**Published date:** 01/22/2025

## Preliminary Information

### PIP6038 Malfunction Indicator Lamp (MIL) Illuminated on Driver Information Center (DIC) - DTC P0442 Set Current or History

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b> <b>from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Buick	Envista	2025	All	All All	All
Chevrolet	Trax	2025	All	All All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<p>Customer may comment that the malfunction indicator lamp is on.</p> <p>Technicians may find DTC P0442 is set as current or history.</p>
<b>Cause</b>	<b>Faulty fuel filler pipe.</b>

#### Correction:

Dealers are to replace the fuel filler pipe.

Refer to SI for the replacement procedure to replace the fuel filler pipe.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

<b>Labor Operation</b>	<b>Description</b>	<b>Labor Time</b>
4028270	Fuel Tank Filler Pipe Replacement	Use Standard Published Labor Time

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>01/22/2025 - Created on.</b>

