

 Preview Solution CBR-2438-1

Volvo Chassis - No-Crank Issue After Programming

Published 31 January 2025

Valid For

Volvo model VN, VAH, VHD

Model Year 2013 to 2024

This CBR solution provides information for resolving no-crank issues after programming.

Issue Overview:

Following the programming of the Vehicle Electronic Control Unit (VECU) or Instrument Cluster, some vehicles may experience a no-crank condition. This issue has been identified as being linked to the activation of the Immobilizer feature, which may prevent the vehicle from starting.

Recommended Action:

To resolve this concern, it is necessary to disable the Immobilizer feature. Please create an E - service with Technical Support for assistance in deactivating this functionality.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article