



Dealer Principal	General Manager	Sales Manager	Service Manager	Parts Manager	Marketing	Finance
Date: January 21, 2025		Source: Aftersales			Replaces: n/a	
Bulletin #: A 01 2025 01		Name:			Supersedes: n/a	
		Title:			Group: n/a	
		Phone #:				
		Email:				

## Aftersales Bulletin

### A 01 2025 01 – Illuminated Treadplates


#### Situation

Rolls-Royce Motor Cars would like to remind our dealer partners to pay attention and take particular care when carrying out the removal or replacement of the illuminated tread plate as they have ribbon cables that may be damaged if handled incorrectly.

#### Information

The tread plate should be gently pried up using an appropriate plastic wedge tool, and then the ribbon cable connector released.

Note: Any subsequent warranty claims for damage to the cable or connector from removal may be rejected.



**Published date** January 21, 2025

**Contact**

If you have further questions, please contact your Regional Aftersales Manager (RAM).