


RCA-78-25-001-1: Reprogram Driver Assistance/Audio/Display Module

Rivian is initiating a customer satisfaction campaign for some model year 2022 R1T and R1S vehicles that were built with programming for early vehicle driver assistance/audio/display module use cases. This programming needs to be updated to allow the customer to use the Google Cast feature of Connect+. No driver assistance features are affected. Rivian will reprogram or replace the affected module. Rivian is launching this campaign for customer satisfaction and to ensure the quality of Rivian vehicles.

Document Type	Customer Satisfaction Campaign Bulletin
Date	January 15, 2025
Affected Region(s)	USA
Affected Model(s)	R1T, R1S
Model Year(s)	2022
Approximate Build Dates	August 2021-September 2022
 Refer to Open Containments in ServiceOS to determine if this document applies to a specific vehicle.	
Vehicle System	78 - Low Voltage Electrical
Minimum Service Location	Service Center

Potentially Required Parts

Part Number	Quantity	Engineering Name	Service Name/Notes
PT00001493-P	1	MODULE - ECU; ADAS/CCDE; AXM	Module, Driver Assistance/Audio/Display

! **Attention:** The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

Required Special Tools:

Tool Number	Tool Name
TSN01569	XMM FUSE CABLE

! **Attention:** The special tools listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional special tools. Always review the bulletin and all potentially related Service Manual procedures before beginning work.

Procedure

Escalate for diagnostic assistance. Using the special tool: Reprogram: Module, Driver Assistance/Audio/Display.

- If reprogramming is successful: No additional work is required.
- If reprogramming is not successful: Replace: Module, Driver Assistance/Audio/Display (refer to service manual procedure 782230010).

Labor Codes

Labor Code	Description
RCA782500100	RCA-78-25-001 not applicable
RCA782500101	Reprogram driver assistance/audio/display module
RCA782500102	Attempt to reprogram assistance/audio/display module, replace module
<i>Contact ServiceDocumentFeedback@rivian.com regarding labor codes and document content.</i>	