

Safety Recall 25KWA: T180/T280/T380/T480 Orscheln Throttle Pedal

 [Edit](#)  [Clone](#)

Number

25KWA / 25V014 / 2025-018

Supplier

Orscheln

Description

Safety Recall 25KWA: T180/T280/T380/T480 Orscheln Throttle Pedal

Date

1/29/2025

What's New

Safety Recall – Interim Notification

Certain vehicles may have an oversized magnet carrier in the throttle pedal assembly. The magnet carrier acts as the pivot for the throttle pedal. An oversized magnet carrier may cause the throttle pedal to stick.

If the throttle pedal fails to return to idle, or sticks, it may increase the risk of a crash.

Drivers may feel sticking or that the pedal doesn't return to idle once released. Pressing the service brake will overcome a stuck throttle pedal and allow the vehicle to stop.

This bulletin will be updated when parts and procedures are available.

Introduction

Safety Recall – Interim Notification

Certain vehicles may have an oversized magnet carrier in the throttle pedal assembly. The magnet carrier acts as the pivot for the throttle pedal. An oversized magnet carrier may cause the throttle pedal to stick.

If the throttle pedal fails to return to idle, or sticks, it may increase the risk of a crash.

Drivers may feel sticking or that the pedal doesn't return to idle once released. Pressing the service brake will

overcome a stuck throttle pedal and allow the vehicle to stop.

Situation

610 (556 US and 54 CAN) Vehicle Model Year 2023-2024 T180 / T280 / T380 / T480 chassis built from 8/18/2022 through 5/8/2023.

Resolution

Safety Recall - Interim Notification

This bulletin will be updated when parts and procedures are available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

[Chassis List](#)

[US Customer Letter](#)

[CAN Customer Letter](#)

Authored by: JB3