


TECHNICAL UPDATE: FUEL TANK FILLER NECK

A technical update has been released to cover a perceived fuel tank filler neck issue in Speed 400 and Scrambler 400 X models.

Models affected: Speed 400, Scrambler 400 X

VIN range: All.

What is the nature of concern? The fuel tank filler neck may appear rusty.



How will this concern be found? Visual inspection upon opening fuel filler cap.

What is the impact to the customer? Visual concern, potential quality perception. No impact to safety or running characteristics of the engine.

What is Triumph doing? We have investigated the concern and found that the fuel cap seal is leaving a residue which looks like rust, though is not actually rust. A revised seal will be released soon.

What do I need to do? Clean the area and inform customers as necessary.

Warranty claim information: Warranty claims for fuel tanks will be rejected.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.