

**On-car analysis list from January 29th, 2025**  
**please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Atlas, Cross Sport	24-25	All	All	MIL-on P0442	Customer states MIL-on, P0442 stored in ECM memory <b>(leak must be from fuel cap area)</b> <b>(Untouched vehicles)</b>
	Atlas, Cross Sport	24-25	All	All	MIL-on P0068	Customer states MIL-on, P0068 stored in ECM memory
<b>Electric</b>	Tiguan	24	All	All	Seat Cover	Customer states the seat cover has discoloration (usually yellowing) stains <b>(Untouched vehicles)</b>
<b>E-Mobility</b>	ID.4	21-24	All	All	CMCe Faults	Customer states Electrical System Error Message, U04A1 [42304], U04A5 [42336], and/or U04A9 [42444] stored in DA:008C <b>(No other relevant DTCs stored in DA:008C)</b>
	ID.4	23-24	All	All	No Start (Tow In)	Customer states vehicle does not start; key not detected. No communication to J519 active. AW 19: U014000[2170894][2240526], B1248F3[1074443], U17B900[8398624] active DTC's <b>(Untouched vehicles)</b>
<b>Body</b>	Tiguan	24	All	All	Striker Plate	Customer states wind noise and or water ingress <b>(Untouched vehicles)</b>
	Atlas, Cross Sport	24-25	All	All	Seat Rattle	Customer states middle row seat rattles <b>(Untouched vehicles)</b>