



# Service Information

Offboard Diagnostic Information System Service (ODIS Service)

Number: VOS-25-11

Subject: ID.Buzz 6A/7A Rear Automatic Door System Hotfix  
Instructions

Date: Jan. 27, 2025

**Important:**

**We recommend installation of this hotfix on one diagnostic device ONLY. Hotfix must be removed immediately after performing the procedure.**

## 1.0 – Introduction

The hotfix is for the ID.Buzz for the 6A/7A rear automatic door system.

The “006A - Basic setting” is not performed completely.

- The wait loop was increased. Please verify the basic setting guided function.

**!! The Hotfix must be removed after performing the diagnostic procedure. !!**

## 2.0 – Prerequisite

ODIS Service **latest Diagnostic Content version** must be installed.


To confirm the installed diagnostic content version in ODIS Service, go to:


Info >  Versions>Diagnostic data; didb\_GFS-v.en\_US: xxxxxxxx **X.XX.XX**




# Service Information

## 3.0 – Download Hotfix

1. Open a **Web Browser** on the diagnostic device and logon to **vwhub.com**
2. Navigate to **Elsa2Go>Service References>Software/Hardware Updates**
3. Search for **ID.Buzz 6A\_7A Hotfix Zip File**
4. Click the **ID.Buzz 6A\_7A Hotfix Zip File**  and **save** it to your Windows desktop.
5. Close your browser.
6. Browse to the desktop and double-click the **ID.Buzz 6A\_7A Hotfix Zip File** to open it.
7. Right click the file (example only) name and select **Copy**:



8. Right click anywhere on the Windows desktop and select **Paste**. This file icon (example) must appear on the desktop:




*(continued)*




# Service Information

## 4.0 – Install Hotfix into ODIS Service

1. Open ODIS Service (“Run as Administrator”)
2. Expand the **Data** submenu and click **Download** (under **Hotfix**):



3. Click **Continue**:




(continued)




# Service Information

- The Directory selection window will appear. Browse to and **highlight the Hotfix file** (*example only*), then click **Select Folder**:



- Click **OK**:



- Perform the diagnostic procedure.

## **Important:**

**The Hotfix must be removed after performing the procedure. Failure to do so will cause other vehicle diagnostics sessions to malfunction.**


(continued)




# Service Information

## 5.0 – Uninstall the Hotfix from ODIS Service

1. Select **Erase** (under Hotfix), then **Continue**:



2. Click **OK** and close ODIS Service:



**Please contact Diagnostic Tester Software Support by phone at 888-896-1298 or email [softwaresupport@vw.com](mailto:softwaresupport@vw.com) with any questions or concerns.**