



Service Bulletin


Bulletin No.: 25-NA-016

Date: January, 2025

INFORMATION

Subject: Information on Underhood Insulator and Beauty Covers/Sight Shields Missing

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	OPTIQ	2025	2025	—	—	All	All

Involved Region or Country	North America, Middle East, Israel, Egypt
Condition	 <p style="text-align: right; font-size: small;">6818428</p> <p>It will be found that the underhood insulator and beauty covers/sight shields are missing during PDI.</p>
Cause	The cause of the condition may be a build change.
Correction	Do not order or install the underhood insulator or beauty covers/sight shields. Insulators and beauty covers/sight shields were deleted for model year 2025.

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool, and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

Parts Information

No parts are required for this repair.

Version	1
Modified	Released January 22, 2025

