

UPS - H524 / N956 VACUUM PIPE BLANKING PLUG - INSPECTION

UPDATE PRIOR TO SALE – H524 / N956 VACUUM PIPE BLANKING PLUG - INSPECTION

AFFECTED MODELS	25MY F-PACE and Range Rover Velar
VOLUME AFFECTED	524 US 41 CAN
REPAIR	On certain JLR vehicles the transportation cap may have been left installed. Retailers are to inspect the vacuum pipe for the transportation cap, if found to be still installed, retailers should remove and install the correct blanking plug.
REPAIR TIME	0.1 hr + DIDO
CAMPAIGN LAUNCH	December 13th, 2024
NOTES	<p>The expected failure rate is approximately 4%, please ensure to preform the inspection first prior to ordering any parts as there is a limited parts quantity available.</p> <p>Retailers are instructed to hold and not sell or deliver any affected vehicles under their control until they are repaired.</p>