



STAR ONLINE PUBLICATION



Case Number: S2508000011

Release Date: February 2025

Symptom/Vehicle Issue: P1CDE-00 - Hybrid/EV Wake-Up Control 2 Output Circuit Short To Battery Set In The Battery Pack Control Module (BPCM)

Discussion: The customer may bring their vehicle in for service because the Red Wrench Service Electrical System lamp is illuminated in the cluster. Upon scanning the vehicle for DTCs you may find P1CDE-00 - Hybrid/EV Wake-Up Control 2 Output Circuit Short To Battery set in the Battery Pack Control Module (BPCM).

P1CDE-00 should be ignored and there will be no effect on vehicle operation or battery performance. Engineering is developing a BPCM software update to change the internal diagnostics that are setting this fault. This software update will be released in the form of a TSB or RSU in late Q1 2025.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found