



Bulletin No.: PIT6332

Published date: 02/5/2025

Preliminary Information

PIT6332 Sound Mode Menu Cannot Be Accessed or Changed

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:	Engine:	Transmissions:
Cadillac	OPTIQ	2025	from to	All	All All All

Involved Region or Country	North America
Additional Options (RPO)	
Condition	Sound mode menu cannot be accessed or changed When attempting to adjust the audio settings within the Sound Mode Menu the screen will flicker, go black and return to the audio settings menu.
Cause	Software

Correction:

Please do not attempt any repairs at this time.

Engineering is aware of the concern and is working on a resolution.

Additional SI Keywords

audio, adjust, display, flash, flashes, menu, mode, options, radio, settings, screen, sound, surround,

Version History

Version	1
Modified	02/05/2025 - Created on.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.