



Bulletin No.: PIP6042

Published date: 02/5/2025

Preliminary Information

PIP6042 Misfire, Rough Idle, MIL Cold Start Only DTC P050D

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Equinox	2025	All	All 1.5 LSD	All
GM	Terrain	2025	All	All 1.5 LSD	All

Involved Region or Country	North America
Condition	Customers may notice a rough idle on initial cold start and potential for CEL/SES Light with P050D setting intermittently.
Cause	Cold start misfire concern more on inclement weather.

Correction:

Engineering is currently investigating. In the meantime, please advise customer they may continue to drive the vehicle. The PI will be updated or replaced with TSB once a determination has been made.

Customer Information

Please communicate to the customer this will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Version History

Version	1
Modified	02/05/2025 - Created on.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.