



# Service Bulletin

Bulletin No.: 25-NA-017

Date: January, 2025

## TECHNICAL

**Subject: Center Console Storage Door Difficult to Open and/or Binding or Stuck**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024	2025	-	-	All	All


<b>Involved Region or Country</b>	United States, Canada, Mexico, Middle East, Israel, Palestine, Argentina (Mercosur), Brazil (Mercosur), Chile (West), Colombia (West), Ecuador (West), Uruguay (West)
<b>Condition</b>	Some customers my comment that the center console storage door is difficult to open, binding or stuck.
<b>Cause</b>	The floor compartment upper panel may be distorting and causing a bind condition.
<b>Correction</b>	Complete the procedure outlined below.

**Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**

**Important:** This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool, and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.

### Service Procedure

Remove the floor console upper panel. Refer to *Front Floor Console Upper Panel Replacement* in Si.



6825579



6825581

Remove the rib with suitable tool from the retention feature pictured above.

Reinstall and check for proper smooth operation.

### Parts Information

No parts are required for this repair.

**Warranty Information**

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*2086978	Remove and Modify Floor Console Upper Panel	1.5 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	Released January 29, 2025

