

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title DIM Message and DTC IEM POA4000		Ref. No. TJ 36905.5.0	
Issuer (Dept.) Technical Service		Issue Date 12/2/24	Status Date 1/29/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3233	
Function Description Electric converter, high voltage		Page Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*Updates to Vehicle Type and Service.

If a customer experiences a DIM message stating "Propulsion System Service Required" and DTC IEM POA4000 is set, please follow the advice under "Service".

DIM = Driver Information Module

DTC = Diagnostic Trouble Code

IEM = Inverter Electric Rear Axle Drive Module

ERAD= Electric Rear Axle Drive

CSC Customer Symptom Codes

Code	Description
53	Driving, Twin Engine/Propulsion using electric motor not possible
7G	Text window and warning symbol/Yellow symbol and text message
IV	Text window and warning symbol/Text message
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
IEM	POA4000	Permanent
IEM	POA4000	Intermittent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	H6	BH6PHEV					2024-2025		-	202346-202447
225	H6	BH6PHEV					2024-2025		-	202346-202447
238	H6	BH6PHEV					2024-2025		-	202346-202447
246	H6	BH6PHEV					2024-2025		-	202346-202447
256	H6	BH6PHEV					2024-2025		-	202346-202447

Technical Journal 36905.5.0

SERVICE:

*A software solution is introduced with version 3.3.16. Perform a software upgrade according to TJ 31543.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
36004-2	Software Control Module downloading

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub-concern area "Support Needed", use function group 3233.