



SSM 53347 2024 Mustang - Convertible - Upper Loadspace Trim Panel Breaking When Operating The Convertible Top

Some 2024 Mustang vehicles equipped with a convertible top may exhibit the upper loadspace trim panel cracking while operating the convertible top. This may be due to the upper loadspace trim panel. To correct this condition, replace the upper loadspace trim panel. A new updated part is available for the right (service part number PR3Z-7631004-BC) and left (service part number PR3Z-7631005-BC) upper loadspace trim panels. For claiming, use causal part 7631005 and applicable labor operations in Section 12 of the Service Labor Time Standards (SLTS) Manual.