



SSM 53349 2025 Aviator - "Drive Control Fault Service Required" Message Displayed In The Instrument Panel Cluster (IPC) Message Center

Some 2025 Aviator vehicles may display a "Drive control fault service required" message in the IPC message center with no applicable diagnostic trouble codes (DTCs) present in the vehicle dynamics control module (VDM). Inform customers that they can clear the fault by cycling the ignition off and on and can continue to drive the vehicle. Engineering is currently working on a solution. Monitor Professional Technician System (PTS) for additional information and schedule service appointments for customers once the repair becomes available.