



SSM 53351 2025 Aviator - Approach Detection Illuminated Entry Inoperative And/Or Reduced Passive Entry Functionality - Built On 11-May-2024 And Through 07-Oct-2024

Some 2025 Aviator vehicles built on 11-May-2024 and through 07-Oct-2024 may exhibit an inoperative approach detection illuminated entry function and/or reduced passive entry functionality. This may be due to the body control module (BCM) configuration. To correct the concern, download and run the "BCM-Body Control Module Installation (PMI)" application using the Ford Diagnostic and Repair System (FDRS) scan tool. For claiming use causal part 15604 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual. Include the Special Service Message (SSM) article number as a subcode in the claim. To assist with the claim, submit a Global Concern Report by using the "Submit Global Concern Report (GCR)" link at the upper right of the OASIS report.