

Newmar Corporation

PO Box 30
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

TSB 611

September 25, 2024

TECHNICAL SERVICE BULLETIN

AFFECTED MODELS

2024 coaches (in production prior to 4/16/24) :: Canyon Star, Kountry Star, Ventana, Super Star, Dutch Star, Supreme Aire, New Aire, Mountain Aire, London Aire, Essex, and King Aire coaches, which are equipped with a Winegard Trav'ler Satellite System and have the auto-stow feature wired for operation.

DESCRIPTION

Winegard has identified an issue with some Trav'ler Pro products when the auto-stow feature is enabled. In a specific scenario, when the auto-stow feature is active, the firmware may occasionally encounter difficulty in recognizing the stowed position. This bulletin supersedes bulletin (607T) now that Winegard has released the firmware update for a complete resolution.

ISSUE

This situation may lead to an occasional unintended stow command when there is a power interruption. This may cause the antenna to lift, rotate, and return to the stowed position.

UNITS AFFECTED

Please refer to the attached population list for affected units and VINs.

CORRECTIVE ACTION

Winegard has now developed a firmware update that needs to be installed. (See the attached links to view the tutorial videos on how to complete this process).

Onboarding a Trav'ler Pro in the RV Halo app (1 minute, 42 seconds)

<https://youtu.be/5otqRWDKCoE?si=tMgOWhMndCrFMjbB>

Updating the Trav'ler Pro software (1 minute, 41 seconds)

<https://youtu.be/F9iZrftwtpB8?si=VWAtvZtZFax3Ge4H>

FLAT RATE CODE: TSB 611 **LABOR TIME:** .15 hr.

NOTE

This is a permanent fix that supersedes the temporary short-term bulletin (607T) intended to eliminate the possibility of the intended stow command. Winegard IDU has new firmware available to fix and add features to the auto stow control and IDU buzzer.

IDU SW: 1.3.5 and ODU SW: v1.17.85

IMPORTANT: Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.

Clarification from Winegard on Update Issues

1. Currently the IDU's WiFi scan will not find any SSID that contains an apostrophe. So a hotspot named Zack's iPhone or Bryan's iPhone would not be listed. (Not ideal, we realize.)
2. The app's progress bar is simply an animation and is not directly proportional to the IDU or ODU progress. The real progress is displayed on the IDU screen.
3. When you see the update start off with an ODU update, that means the antenna (ODU) and IDU control box have Firmware mismatched from the Newmar plant. This happens when an IDU on older firmware gets installed with an antenna on newer firmware. When the tech sees the TSB update process begin with an ODU download the tech is witnessing is the IDU rolling back the ODU firmware to an older but compatible version of firmware. This roll back does not require internet access. The ODU firmware and installer reside permanently in the IDU. This roll back feature exists should an antenna need replacement years in the future, the original IDU can ensure the ODU antenna is rolled back to compatible firmware. (Antenna and IDU need compatible firmware to ensure accurate app control). As of June 2024, the factory keeps the IDU and antenna as a matching set.
4. When the QR code does not allow app pairing, it's because someone has already paired a device to that IDU. If that someone forgets to press "Remove Device from RV" in the app, it will prevent a second person from pairing to the IDU. Winegard uses a bonded Bluetooth pairing with secure key. That's how we prevent unauthorized persons from pairing to a customer's Travler Pro IDU. If a tech runs into this issue, pressing and holding the reset button on the back of IDU until the IDU display goes dark is the only way to purge the pairing key. Once the pairing key is purged from IDU, a new user can then scan the QR and pair to the IDU.
5. Any non-mismatched IDU / ODU will upgrade straight to the newest firmware versions. There are no sequential update hops. (The explanation in item 3 above clarifies things.)
6. Once the IDU update is complete (download, installation, reboot), internet access is no longer required. The ODU update is ready and waiting inside the updated IDU. The tech just needs to start the ODU update via app.
7. Both IDU and ODU updates are needed to satisfy the TSB and ensure proper Auto Stow functionality.
8. Cloud icon on IDU must illuminate. An illuminated Cloud icon indicates the IDU has internet access to Winegard's upgrade server. The "!" exclamation point inside the Cloud icon indicates there is an update job available for download. I have seen some WiFi networks prevent connectivity to the Winegard upgrade server, so the cloud icon never illuminates. Newmar's Guest network is an example. That network allows general internet access, but blocks lots of things. So, keep in mind that a dealership may never get the cloud to illuminate on an IDU. If this is the case, it's something on their network (an IT rule or restriction) preventing the connection.

9. We don't allow the IDU to connect to an open unsecured network. We don't want our firmware payload transmitted across an unsecured network.
10. The ODU update is slower than the IDU's. That is normal behavior. The ODU update is transmitted up the 6 pin control cable that connects the IDU to the ODU. We have to run a slower baud rate to ensure data transmission accuracy.
11. There were concerns expressed about ODU update starting first. Number 3 explains the how and why.
12. The only time a Travler Pro antenna autostow event will begin is when these 4 criteria are met: Travler Pro IDU has AC power, IDU displays "Not Stowed," the coach engine is running, and the park brake is released.
13. The tech (or owner) can also see Firmware versions from screen of IDU. I find that easier than using app.

Hopefully this helps clarify edge case behavior. Remember, once the IDU completes the download, install, and reboot; internet is not needed for the ODU update. This should streamline the process and efficiency. Don't hesitate to reach out.

Bryan Holmes

Lead Technical Manager, Winegard

2736 Mt. Pleasant St., Burlington, IA 52601

[319.758.5876](tel:319.758.5876) o [574.536.9221](tel:574.536.9221) m

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
USA Units								
	162974 4UZACMFCXRCUM4594	2024	CS	FD		3947 FL	1/24/2023	2/2/2023
	163002 4UZACMFC0RCVH5951	2024	CS	FD		3947 FL	10/16/2023	10/24/2023
	163003 4UZACMFC2RCVH5952	2024	CS	FD		3947 FL	10/23/2023	11/1/2023
	163004 4UZACMFC3RCVE7562	2024	CS	FD		3957 FL	8/9/2023	8/18/2023
	163005 4UZACMFC0RCVG3170	2024	CS	FD		3947 FL	9/6/2023	9/14/2023
	230489 1FVACYFE0PHNX5194	2024	SS	CC		3731 FS	11/17/2022	11/29/2022
	230525 1FVACYFE4PHNX5196	2024	SS	CC		4059 FS	2/21/2023	3/1/2023
	230544 1FVACYFE5RHVA6757	2024	SS	CC		3731 FS	10/3/2023	10/12/2023
	230545 1FVACYFE2RHUR6449	2024	SS	CC		3731 FS	10/12/2023	10/20/2023
	230547 1FVACYFE2RHVA6764	2024	SS	CC		4059 FS	11/1/2023	11/9/2023
	230548 1FVACYFE2RHVA6750	2024	SS	CC		4059 FS	11/7/2023	11/14/2023
	230552 1FVACYFE2RHVA6747	2024	SS	CC		3727 FS	8/1/2023	8/10/2023
	230567 1FVACYFEXRHVA6754	2024	SS	CC		4059 FS	10/5/2023	10/13/2023
	230571 1FVACYFE4RHUR6467	2024	SS	CC		4059 FS	12/19/2023	1/16/2024
	230572 1FVACYFE7RHVA6744	2024	SS	CC		4059 FS	9/7/2023	9/26/2023
	230573 1FVACYFE9RHVA6759	2024	SS	CC		4061 FS	11/15/2023	11/29/2023
	230574 1FVACYFE9RHUR6464	2024	SS	CC		3727 FS	12/15/2023	1/11/2024
	230581 1FVACYFE3RHUR6444	2024	SS	CC		3727 FS	10/18/2023	10/26/2023
	230583 1FVACYFE4RHUR6436	2024	SS	CC		4059 FS	11/21/2023	12/4/2023
	230584 1FVACYFE3RHUR6461	2024	SS	CC		3731 FS	11/6/2023	11/14/2023
	230585 1FVACYFE1RHVA6755	2024	SS	CC		4065 FS	10/10/2023	10/18/2023
	230592 1FVACYFE8RHUR6438	2024	SS	CC		4059 FS	12/4/2023	12/13/2023
	230602 1FVACYFE3RHUR6475	2024	SS	CC		4059 FS	2/15/2024	2/27/2024
	230603 3ALACYFE7RDVE7980	2024	SS	CC		3731 FS	2/14/2024	2/21/2024
	230606 1FVACYFE6RHUR6485	2024	SS	CC		4059 FS	2/12/2024	2/20/2024
	270221 1FVHC5DV7PHNY4023	2024	SA	CC		4530 FS	12/14/2022	1/10/2023
	270240 1FVHC5DV9PHNY4024	2024	SA	CC		4051 FS	1/26/2023	2/6/2023
	270246 1FVHC5DV0RHVA6763	2024	SA	CC		4051 FS	10/9/2023	10/17/2023
	270247 1FVHC5DV7RHVA6758	2024	SA	CC		4530 FS	9/28/2023	10/9/2023
	270248 1FVHC5DV8RHVA6753	2024	SA	CC		4530 FS	7/31/2023	8/9/2023
	270253 1FVHC5DV4RHVA6748	2024	SA	CC		4530 FS	7/19/2023	7/27/2023
	270258 1FVHC5DV6RHUR6454	2024	SA	CC		4051 FS	11/9/2023	11/17/2023
	270259 1FVHC5DV0RHUR6451	2024	SA	CC		4530 FS	11/29/2023	12/11/2023
	270262 1FVHC5DV6RHUR6440	2024	SA	CC		4530 FS	10/30/2023	11/7/2023
	270269 1FVHC5DV4RHUR6453	2024	SA	CC		4530 FS	11/16/2023	11/30/2023
	270272 1FVHC5DV1RHUR6460	2024	SA	CC		4051 FS	2/29/2024	3/19/2024
	270274 1FVHC5DV4RHUR6470	2024	SA	CC		4530 FS	2/15/2024	2/27/2024
	416286 4VZAT1D11RC093626	2024	VT	DP		4369 S	2/6/2023	2/14/2023
	416288 4UZACHFEXRCUM8959	2024	VT	DP		3512 FL	2/23/2023	3/7/2023
	416292 4UZFCHF8RCUM8979	2024	VT	DP		4037 FL	2/21/2023	3/1/2023
	416293 4VZAT1D15RC093631	2024	VT	DP		3809 S	3/7/2023	3/15/2023
	416302 4VZAT1D10PC093632	2024	VT	DP		4369 S	3/28/2023	4/17/2023
	416328 4VZAT1D14RC095175	2024	VT	DP		3809 S	6/16/2023	7/12/2023
	416329 4VZAT1D12RC095174	2024	VT	DP		4037 S	6/16/2023	7/13/2023
	416330 4VZAT1D19RC095172	2024	VT	DP		4326 S	6/19/2023	7/14/2023
	416331 4VZAT1D10RC095173	2024	VT	DP		4369 S	6/22/2023	7/19/2023
	416348 4UZFCHF6PCUR3559	2024	VT	DP		4369 FL	10/18/2023	10/26/2023
	416351 4UZFCHF4PCUS0691	2024	VT	DP		4369 FL	9/1/2023	9/12/2023
	416352 4UZFCHF9PCUZ3040	2024	VT	DP		4310 FL	7/18/2023	7/26/2023

416354	4UZACHFE0RCVJ6427	2024	VT	DP	3512	FL	10/30/2023	11/8/2023
416355	4UZACHFE6RCVJ7596	2024	VT	DP	3809	FL	10/24/2023	11/2/2023
416356	4UZFCHFE7RCVJ7595	2024	VT	DP	4068	FL	10/23/2023	11/1/2023
416357	4UZFCHFE3RCVJ7593	2024	VT	DP	4369	FL	10/23/2023	11/1/2023
416358	4UZFCHFE2PCUR1534	2024	VT	DP	4310	FL	10/17/2023	10/25/2023
416361	4VZAT1D17RC095364	2024	VT	DP	4369	S	11/13/2023	11/20/2023
416362	4VZAT1D14RC095421	2024	VT	DP	4037	S	12/6/2023	12/15/2023
416363	4VZAT1D19RC095480	2024	VT	DP	4369	S	1/11/2024	1/23/2024
416364	4VZAT1D13RC095393	2024	VT	DP	4369	S	11/30/2023	12/11/2023
416365	4VZAT1D19RC095365	2024	VT	DP	4326	S	11/13/2023	11/20/2023
416371	4VZAT1D16RC095291	2024	VT	DP	4369	S	9/28/2023	10/9/2023
416378	4UZFCHFE0RCVL2844	2024	VT	DP	4037	FL	12/12/2023	12/20/2023
416379	4UZFCHFE2RCVL9133	2024	VT	DP	4037	FL	12/20/2023	1/16/2024
416380	4UZACHFE8RCVN8618	2024	VT	DP	3809	FL	2/8/2024	2/15/2024
416383	4UZFCHFE1RCVM4453	2024	VT	DP	4369	FL	12/15/2023	1/10/2024
416386	4UZACHFE5RCVJ8528	2024	VT	DP	3809	FL	11/1/2023	11/10/2023
416389	4UZFCHFE4PCUS8760	2024	VT	DP	4369	FL	2/1/2024	2/9/2024
416394	4UZFCHFE9RCVL2843	2024	VT	DP	4369	FL	1/31/2024	2/8/2024
416395	4VZAT1D12RC095501	2024	VT	DP	4037	S	1/24/2024	2/2/2024
416405	4UZACHFE2RCVN5827	2024	VT	DP	3817	FL	1/31/2024	2/8/2024
416412	4UZFCHFE3PCUV1124	2024	VT	DP	4037	FL	2/9/2024	2/19/2024
502121	4VZVU1R19RC093624	2024	LA	DP	4551	S	2/1/2023	2/9/2023
502126	4VZVU1R14RC093630	2024	LA	DP	4569	S	2/15/2023	2/27/2023
502140	4VZVU1R10RC095214	2024	LA	DP	4521	S	8/9/2023	8/18/2023
502141	4VZVU1R11RC095285	2024	LA	DP	4535	S	10/5/2023	10/13/2023
502142	4VZVU1R14RC095216	2024	LA	DP	4535	S	8/17/2023	8/29/2023
502143	4VZVU1R14RC095202	2024	LA	DP	4551	S	7/27/2023	8/8/2023
502144	4VZVU1R16RC095184	2024	LA	DP	4551	S	7/24/2023	8/1/2023
502145	4VZVU1R14RC095166	2024	LA	DP	4551	S	7/17/2023	7/25/2023
502149	4VZVU1R12RC095165	2024	LA	DP	4569	S	6/19/2023	7/13/2023
502152	4VZVU1R1XRC095298	2024	LA	DP	4551	S	10/11/2023	10/19/2023
502163	4VZVU1R17RC095209	2024	LA	DP	4551	S	8/3/2023	8/15/2023
502165	4VZVU1R15RC095239	2024	LA	DP	4551	S	8/30/2023	9/8/2023
502168	4VZVU1R12RC095425	2024	LA	DP	4551	S	12/7/2023	12/18/2023
502169	4VZVU1R19RC095387	2024	LA	DP	4569	S	11/21/2023	12/5/2023
502173	4VZVU1R15RC095354	2024	LA	DP	4535	S	11/13/2023	11/20/2023
502174	4VZVU1R16RC095427	2024	LA	DP	4569	S	12/15/2023	1/10/2024
502175	4VZVU1R16RC095444	2024	LA	DP	4521	S	1/10/2024	1/22/2024
502176	4VZVU1R14RC095443	2024	LA	DP	4551	S	12/21/2023	1/18/2024
502181	4VZVU1R16RC095346	2024	LA	DP	4551	S	11/9/2023	11/17/2023
502182	4VZVU1R10RC095424	2024	LA	DP	4551	S	12/6/2023	12/15/2023
502188	4VZVU1R11RC095545	2024	LA	DP	4551	S	2/15/2024	2/27/2024
502192	4VZVU1R1XRC095561	2024	LA	DP	4551	S	2/28/2024	3/18/2024
502195	4VZVU1R18RC095512	2024	LA	DP	4535	S	2/6/2024	2/13/2024
502196	4VZVU1R14RC095605	2024	LA	DP	4551	S	3/20/2024	4/11/2024
502198	4VZVU1R13RC095546	2024	LA	DP	4535	S	2/19/2024	2/29/2024
530776	4VZVU1R14RC093627	2024	KG	DB	4531	S	1/26/2023	2/6/2023
530782	4VZVU1R18RC095137	2024	KG	DB	4531	S	7/19/2023	7/27/2023
530783	4VZVU1R17RC095128	2024	KG	DB	4596	S	6/19/2023	7/13/2023
530797	4VZVU1R17RC095212	2024	KG	DB	4531	S	8/31/2023	9/12/2023
530799	4VZVU1R11RC095304	2024	KG	DB	4558	S	10/13/2023	10/23/2023

530800	4VZVU1R17RC095422	2024	KG	DB	4521	S	12/12/2023	12/20/2023
530801	4VZVU1R15RC095385	2024	KG	DB	4531	S	11/29/2023	12/7/2023
530802	4VZVU1R15RC095290	2024	KG	DB	4521	S	9/27/2023	10/6/2023
530806	4VZVU1R10RC095441	2024	KG	DB	4531	S	12/19/2023	1/12/2024
611301	4VZAU1D18RC093622	2024	DS	DP	4370	S	1/17/2023	1/25/2023
611311	4UZFCHFE0RCUM8961	2024	DS	DP	4071	FL	2/23/2023	3/7/2023
611316	4UZFCHFE4RCUM8980	2024	DS	DP	4369	FL	3/16/2023	3/29/2023
611340	4UZFCHFE0PCUS0686	2024	DS	DP	4325	FL	7/24/2023	8/1/2023
611341	4UZFCHFE3PCUR3549	2024	DS	DP	4325	FL	7/17/2023	7/25/2023
611342	4UZFCHFE3PCUR3552	2024	DS	DP	4325	FL	7/19/2023	7/27/2023
611343	4UZFCHFE3PCUV1110	2024	DS	DP	4369	FL	7/24/2023	8/2/2023
611344	4UZFCHFE5PCUP6364	2024	DS	DP	4369	FL	7/19/2023	7/27/2023
611345	4UZFCHFE7PCUT8960	2024	DS	DP	4369	FL	7/26/2023	8/3/2023
611346	4UZFCHFE2PCUS0690	2024	DS	DP	4326	FL	7/20/2023	7/31/2023
611349	4UZACHFE6RCVF2117	2024	DS	DP	3836	FL	8/30/2023	9/8/2023
611351	4UZFCHFE4PCUN8650	2024	DS	DP	4081	FL	7/26/2023	8/7/2023
611352	4UZFCHFE1RCVJ7589	2024	DS	DP	4081	FL	10/23/2023	11/1/2023
611353	4UZFCHFE0RCVH2840	2024	DS	DP	4081	FL	9/12/2023	9/28/2023
611374	4UZACHFE8RCVE0731	2024	DS	DP	3836	FL	8/17/2023	8/29/2023
611376	4VZAU1D10RC095171	2024	DS	DP	4081	S	6/19/2023	7/14/2023
611377	4VZAU1D11PC094530	2024	DS	DP	4325	S	7/11/2023	7/19/2023
611378	4VZAU1D11RC094529	2024	DS	DP	4369	S	6/20/2023	7/13/2023
611384	4UZFCHFE7PCUV1109	2024	DS	DP	4369	FL	8/7/2023	8/16/2023
611385	4UZFCHFE9PCUX8022	2024	DS	DP	4369	FL	10/6/2023	10/16/2023
611386	4UZFCHFE4PCUS0688	2024	DS	DP	4369	FL	7/21/2023	8/1/2023
611387	4UZFCHFE3RCVH5943	2024	DS	DP	4081	FL	9/26/2023	10/5/2023
611421	4UZACHFE1RCVJ6422	2024	DS	DP	3836	FL	10/24/2023	11/2/2023
611422	4UZFCHFE9PCUY6718	2024	DS	DP	4369	FL	9/7/2023	9/26/2023
611429	4UZFCHFE6PCUX8026	2024	DS	DP	4081	FL	8/3/2023	8/15/2023
611430	4VZAU1D13PC094531	2024	DS	DP	4326	S	7/31/2023	8/9/2023
611443	4UZFCHFE2PCUX8024	2024	DS	DP	4081	FL	8/2/2023	8/14/2023
611451	4UZFCHFE5PCUX8017	2024	DS	DP	4325	FL	8/16/2023	8/28/2023
611453	4UZACHFE4RCVE6185	2024	DS	DP	3836	FL	8/14/2023	8/22/2023
611456	4VZAU1D18PC094606	2024	DS	DP	4369	S	8/22/2023	9/1/2023
611457	4VZAU1D14PC094750	2024	DS	DP	4369	S	9/12/2023	10/2/2023
611458	4VZAU1D1XRC095419	2024	DS	DP	4369	S	12/1/2023	12/12/2023
611459	4VZAU1D19RC095363	2024	DS	DP	4081	S	11/15/2023	11/22/2023
611460	4VZAU1D15RC095277	2024	DS	DP	4369	S	10/11/2023	10/20/2023
611461	4VZAU1D11RC095325	2024	DS	DP	4325	S	10/23/2023	11/1/2023
611471	4VZAU1D15RC095361	2024	DS	DP	4071	S	11/13/2023	11/21/2023
611472	4VZAU1D1XRC095310	2024	DS	DP	4310	S	10/16/2023	10/24/2023
611474	4VZAU1D15RC095358	2024	DS	DP	4369	S	11/15/2023	11/29/2023
611481	4UZFCHFE2RCVG5520	2024	DS	DP	4081	FL	8/29/2023	9/7/2023
611485	4UZFCHFE5PCUV1111	2024	DS	DP	4369	FL	8/21/2023	8/31/2023
611489	4UZFCHFE6RCVJ8527	2024	DS	DP	4081	FL	11/9/2023	11/17/2023
611495	4UZACHFE0RCVJ4676	2024	DS	DP	3817	FL	10/13/2023	10/23/2023
611502	4UZACHFE3RCVJ6423	2024	DS	DP	3817	FL	10/31/2023	11/9/2023
611503	4UZACHFE7RCVP3630	2024	DS	DP	3836	FL	1/26/2024	2/5/2024
611504	4UZFCHFEXRCVN8612	2024	DS	DP	4081	FL	2/9/2024	2/16/2024
611507	4UZFCHFEXRCVM4449	2024	DS	DP	4325	FL	12/14/2023	1/9/2024
611508	4UZFCHFE6RCVL9121	2024	DS	DP	4325	FL	12/5/2023	12/14/2023

611509	4UZFCHFEXRCVN5824	2024	DS	DP	4369	FL	1/11/2024	1/23/2024
611510	4UZFCHFE5RCVL2841	2024	DS	DP	4369	FL	12/12/2023	12/21/2023
611511	4UZFCHFE1RCVL9124	2024	DS	DP	4369	FL	12/13/2023	12/21/2023
611524	4VZAU1D11RC095342	2024	DS	DP	4369	S	11/2/2023	11/13/2023
611539	4UZFCHFE2RCVK6690	2024	DS	DP	4310	FL	1/19/2024	1/29/2024
611540	4UZFCHFE7RCVL2842	2024	DS	DP	4326	FL	12/13/2023	1/9/2024
611543	4VZAU1D18RC095449	2024	DS	DP	4369	S	1/10/2024	1/23/2024
611554	4VZAU1D16RC095479	2024	DS	DP	4369	S	1/24/2024	2/1/2024
611562	4UZFCHFE8RCVP5330	2024	DS	DP	4369	FL	2/28/2024	3/18/2024
611563	4UZFCHFE1RCVP5329	2024	DS	DP	4310	FL	2/20/2024	3/5/2024
611565	4VZAU1D10RC095557	2024	DS	DP	4369	S	2/20/2024	3/5/2024
711533	4VZAT1D10RC093620	2024	NA	DP	3539	S	12/15/2022	1/11/2023
711540	4UZACEFE8RCUM8957	2024	NA	DP	3547	FL	2/13/2023	2/22/2023
711559	4VZAT1D17PC094566	2024	NA	DP	3547	S	7/11/2023	7/25/2023
711565	4VZAT1D19RC095169	2024	NA	DP	3543	S	8/16/2023	8/28/2023
711566	4VZAT1D17PC094938	2024	NA	DP	3543	S	7/24/2023	8/2/2023
711568	4UZACEFE0RCVK3120	2024	NA	DP	3543	FL	11/21/2023	12/5/2023
711575	4VZAT1D15RC095170	2024	NA	DP	3549	S	8/29/2023	9/8/2023
711580	4VZAT1D10RC095349	2024	NA	DP	3539	S	11/6/2023	11/14/2023
711582	4UZACEFE4RCVF2115	2024	NA	DP	3547	FL	10/11/2023	10/19/2023
711583	4UZACEFE3RCVJ7585	2024	NA	DP	3543	FL	12/7/2023	12/19/2023
711584	4UZACEFE4RCVJ8521	2024	NA	DP	3543	FL	11/8/2023	11/15/2023
711585	4UZACEFE4RCVK0429	2024	NA	DP	3543	FL	11/14/2023	11/22/2023
711586	4UZACEFE4RCVK3122	2024	NA	DP	3547	FL	11/30/2023	12/11/2023
711587	4UZACEFE2RCVK0428	2024	NA	DP	3547	FL	11/9/2023	11/17/2023
711593	4VZAT1D10RC095447	2024	NA	DP	3547	S	1/10/2024	1/22/2024
711595	4UZACEFE7RCVL9119	2024	NA	DP	3543	FL	1/11/2024	1/24/2024
711601	4VZAT1D1XRC095505	2024	NA	DP	3547	S	2/12/2024	2/19/2024
711602	4VZAT1D17RC095607	2024	NA	DP	3547	S	3/6/2024	4/9/2024
711603	4VZAT1D16RC095565	2024	NA	DP	3539	S	3/20/2024	4/12/2024
711604	4VZAT1D14RC095550	2024	NA	DP	3539	S	2/21/2024	3/6/2024
711605	4VZAT1D11RC095506	2024	NA	DP	3547	S	2/13/2024	2/20/2024
711606	4UZACEFE5SCVS9467	2024	NA	DP	3539	FL	3/7/2024	3/26/2024
711607	4VZAT1D1XRC095553	2024	NA	DP	3547	S	2/29/2024	3/19/2024
711608	4VZAT1D16RC095551	2024	NA	DP	3547	S	2/27/2024	3/8/2024
711615	4UZACEFE1RCVP3623	2024	NA	DP	3543	FL	2/7/2024	2/15/2024
750910	4UZACHFC6RCUM8956	2024	KS	DP	3418	FL	1/30/2023	2/7/2023
750928	4UZACHFC3PCUS0710	2024	KS	DP	3418	FL	6/16/2023	7/12/2023
750942	4UZACHFC6PCUV1126	2024	KS	DP	4011	FL	10/9/2023	10/18/2023
750943	4UZACHFC2PCUP8484	2024	KS	DP	3717	FL	9/27/2023	10/6/2023
801570	4VZVU1R13RC093621	2024	EX	DP	4595	S	11/16/2022	11/28/2022
801592	4VZVU1R18RC093629	2024	EX	DP	4521	S	2/22/2023	3/6/2023
801602	4VZVU1R10RC095164	2024	EX	DP	4551	S	7/18/2023	7/26/2023
801603	4VZVU1R12RC095182	2024	EX	DP	4521	S	7/25/2023	8/2/2023
801604	4VZVU1R11RC095237	2024	EX	DP	4551	S	8/22/2023	9/1/2023
801605	4VZVU1R16RC095282	2024	EX	DP	4569	S	9/28/2023	10/10/2023
801617	4VZVU1R19RC095213	2024	EX	DP	4551	S	8/15/2023	8/23/2023
801619	4VZVU1R13RC095272	2024	EX	DP	4595	S	9/14/2023	10/3/2023
801620	4VZVU1R14RC095345	2024	EX	DP	4595	S	10/30/2023	11/8/2023
801621	4VZVU1R1XRC095494	2024	EX	DP	4551	S	1/24/2024	2/1/2024
801626	4VZVU1R12RC095442	2024	EX	DP	4595	S	12/6/2023	12/15/2023

801631	4VZVU1R15RC095502	2024 EX	DP	4551 S	1/29/2024	2/6/2024
801632	4VZVU1R15RC095452	2024 EX	DP	4551 S	1/19/2024	1/29/2024
801633	4VZVU1R11RC095559	2024 EX	DP	4521 S	2/9/2024	2/19/2024
801636	4VZVU1R18RC095543	2024 EX	DP	4551 S	2/16/2024	2/28/2024
905097	4VZVU1E19RC093628	2024 MA	DP	3823 S	1/31/2023	2/9/2023
905100	4VZVU1E18RC093619	2024 MA	DP	4551 S	2/23/2023	3/6/2023
905106	4VZVU1E10RC095168	2024 MA	DP	3825 S	7/18/2023	7/26/2023
905107	4VZVU1E12RC095186	2024 MA	DP	3825 S	7/26/2023	8/7/2023
905111	4VZVU1E19RC095167	2024 MA	DP	4118 S	6/16/2023	7/12/2023
905114	4VZVU1R17RC095274	2024 MA	DP	4551 S	9/14/2023	10/4/2023
905115	4VZVU1E1XRC095355	2024 MA	DP	4118 S	11/6/2023	11/14/2023
905117	4VZVU1E13RC095357	2024 MA	DP	3823 S	11/15/2023	11/22/2023
905119	4VZVU1E10RC095431	2024 MA	DP	3825 S	12/6/2023	12/18/2023
905135	4VZVU1E19RC095203	2024 MA	DP	4118 S	8/1/2023	8/10/2023
905136	4VZVU1E18RC095323	2024 MA	DP	4118 S	10/24/2023	11/2/2023
905137	4VZVU1E11RC095308	2024 MA	DP	4118 S	10/20/2023	10/31/2023
905138	4VZVU1E16RC095241	2024 MA	DP	4551 S	8/23/2023	9/5/2023
905139	4VZVU1E10RC095347	2024 MA	DP	4551 S	10/31/2023	11/8/2023
905145	4VZVU1E12RC095267	2024 MA	DP	3825 S	9/1/2023	9/12/2023
905151	4VZVU1E19RC095430	2024 MA	DP	4118 S	12/13/2023	12/21/2023
905154	4VZVU1E10RC095445	2024 MA	DP	4551 S	12/21/2023	1/18/2024
905155	4VZVU1E11RC095454	2024 MA	DP	4551 S	1/12/2024	1/24/2024
905160	4VZVU1E12RC095446	2024 MA	DP	4118 S	12/18/2023	1/11/2024
905164	4VZVU1E12RC095477	2024 MA	DP	3825 S	1/25/2024	2/2/2024
905169	4VZVU1E12RC095432	2024 MA	DP	3825 S	1/9/2024	1/19/2024
905170	4VZVU1E13RC095455	2024 MA	DP	3825 S	1/10/2024	1/22/2024
905174	4VZVU1E18RC095547	2024 MA	DP	4551 S	3/5/2024	3/25/2024

Canadian Units

230557	1FVACYFE6RHVA6749	2024 SS	CC	4059 FS	6/20/2023	7/13/2023
502183	4VZVU1R1XRC095513	2024 LA	DP	4551 S	2/12/2024	2/19/2024
611304	4UZACHFE8RCUM8958	2024 DS	DP	3836 FL	2/23/2023	3/7/2023
711569	4UZACEFE4RCVE6184	2024 NA	DP	3543 FL	10/17/2023	10/25/2023
905070	4VZVU1E13RC093625	2024 MA	DP	3825 S	10/31/2022	11/17/2022
905144	4VZVU1E17RC095250	2024 MA	DP	4118 S	8/29/2023	9/7/2023