

Title: BL1075/BL1076 update

Applicability: Revero GT and GTS, GS-6 vehicles


Market Region: All

PRIORITY: All


PURPOSE: A software update for Karma Vehicles to connect to the current servers for future over-the-air -updates

Vehicles in the field will all receive this update over the air. Should this update not be accepted, create a TSS case and follow the representative guidance to update the vehicle manually. The software installed for the CIU is K1-21-1075.RC1 for Revero GT and GS-6 and K1-21-1076.RC1 for Revero GTS/ GS-6 Sport motor variants.

When the prompt is received accept the download and wait for the vehicle to complete the process.



The new CIU ID should now read 21.35.52.2.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Title: BL1075/BL1076 update

Applicability: Revero GT and GTS, GS-6 vehicles

Market Region: All

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY
N/A	N/A	N/A

Please contact the parts department (parts@karmaautomotive.com) and order this part by email if not available in on-line at time of repair.

SHOP SUPPLIES:

DESCRIPTION
N/A

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART: (use one of the parts for the complaint)

PART NUMBER	DESCRIPTION
N/A	N/A

LABOR CODES: (use one appropriate for the part(s) replaced)

CODE	DESCRIPTION	TIME	DEFECT CODE
00-99-20-72	BL1075 Update	0.5	99-20-20-68

SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A		

WARRANTY DISPOSITION: This repair is covered under the New Vehicle Limited Warranty, in effect for four (4) years from the in-service date with unlimited mileage limitation for Revero GT and GTS, 4 years/50K miles for GS-6.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.