



# Service Bulletin

Bulletin No.: 25-NA-024

Date: February, 2025

## INFORMATION

**Subject: Trailer Lighting Inoperative After Accessory Hitch Installed**

**This Bulletin replaces PIT6271A. Please discard PIT6271A.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2025	2025	-	-	All	All
GMC	Terrain	2025	2025	-	-	All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	Some customers/technicians may comment that after hitch installation, the trailer lighting is inoperative.
<b>Cause</b>	The cause of the condition may be a calibration being required for the lighting control module to activate the lighting to the trailering connector.
<b>Correction</b>	The installation instructions have been updated to include the need for the Lighting Control Module calibration update. The instruction sheets will contain the authorization codes. Refer to "Trailer Hitch Platform Package Installation" in the Accessory Installation Manual.

**Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.**

### Parts Information

No parts are required for this repair.

<b>Version</b>	1
<b>Modified</b>	Released February 06, 2025

