



**Bulletin No.:** PIT6280A

**Published date:** 02/12/2025

## Preliminary Information

### PIT6280A Illuminated Perimeter Rocker Lighting Inoperative

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet Blazer EV		2025	All All	All	All
Chevrolet Silverado EV		2025	All All	All	All
GMC Sierra Denali EV		2025	All All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Additional Options (RPO)</b>	<b>S3I</b>
<b>Condition</b>	<b>Dealer installed accessory perimeter rocker panel lighting kit is inoperative.</b>
<b>Cause</b>	<b>Software Anomaly</b>

#### Correction:

To correct this concern reprogram the K9 BCM and the K219 Lighting Control Module with the latest calibrations in TLC/SPS.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage.


<b>Labor Operation</b>	<b>Description</b>	<b>Labor Time</b>
<b>2810215</b>	<b>Body Control Module Reprogramming with SPS</b>	<b>Use Published Labor Time</b>
<b>2811105</b>	<b>Lighting Control Module Reprogramming with SPS</b>	<b>Use Published Labor Time</b>

#### Additional SI Keywords

accessory, dealer, ground, lamp, inop, inoperative, installed, light, lighting, lights, panel, puddle, rocker, SPO

#### Version History

<b>Version</b>	<b>2</b>
<b>Modified</b>	<b>11/08/2024 - Created on. 02/12/2025- Updated to add software fix to the PI</b>

 GM Global Brands

© 2025 General Motors. All Rights Reserved.