



**Bulletin No.:** PIC6593

**Published date:** 02/13/2025

## Preliminary Information

### PIC6593 DTC P0621 - Service Charging System Displayed

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b> from to	<b>Engine:</b>	<b>Transmissions:</b>
Buick	Encore GX	2024 - 2025	All	All All	All
Buick	Envista	2024 - 2025	All	All All	All
Chevrolet	Trailblazer	2024 - 2025	All	All All	All
Chevrolet	Trax	2024 - 2025	All	All All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<p><b>Customers may comment that the CEL/MIL is illuminated along with a service charging system message.</b></p> <p><b>Technician may find DTC P0621 set as current or history.</b></p>
<b>Cause</b>	<b>Engineering is currently investigating.</b>

#### Correction:

**Please follow the diagnostic test procedures outlined in SI for DTC P0621.**

**If the test results do not directly identify a functional fault, other than a warning message/light, do NOT replace any parts at this time.**

**Engineering is currently investigating.**

**In the meantime, please advise customer they may continue to drive the vehicle**

**The PI will be updated or replaced with TSB once a determination has been made.**

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>02/13/2025 - Created on.</b>