



Bulletin No.: PIP6045

Published date: 02/14/2025

Preliminary Information

PIP6045 Diagnostic Tip: Chirp Noise Heard From Inside Engine Compartment

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All	All 2.5 LK0	All
Chevrolet	Traverse	2024 - 2025	All	All 2.5 LK0	All
GMC	Acadia	2024 - 2025	All	All 2.5 LK0	All

Involved Region or Country:	North America
Condition:	Chirp noise heard from engine compartment
Cause:	Engineering currently investigating root cause

Correction

If you encounter a chirp type noise coming that is coming from inside the engine do not attempt any repairs at this time as Engineering is currently investigating the root cause of the condition.

Note: This noise may be intermittent in nature and is not temperature dependent. Reference audio file below for chirp noise.

SEE Service Information or attached video below

6833913 Video

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description	Labor Time:
* 4089468	Diagnose Engine Chirp Noise	0.3 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	02/14/2025 - Created on.

Attachments

- [chirp.mp4](#)

GM Global Brands

© 2025 General Motors. All Rights Reserved.