

## Technical Service Bulletin (TSB) Missing Keyfob With Remote Control

<b>REFERENCE:</b>	<b>TSB:</b> 08-036-25 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	February 15, 2025	<b>REVISION:</b>	-
<b>VEHICLES AFFECTED:</b>	<b>2025 (GC) Alfa Romeo Tonale</b> This bulletin applies to vehicles built on or before <b>December 31, 2024</b> (MDH 1231XX).			<b>MARKET APPLICABILITY:</b>	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience the following:</b> <ul style="list-style-type: none"> <li>Second key fob is missing.</li> </ul>				
<b>CAUSE:</b>	Plant sequencing issue				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-017, date of issue February 15, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

### REPAIR SUMMARY:

This bulletin involves ordering a new keyfob and handing the it to the customer or placing it in the vehicle.

### CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-80-44-97	Transmitter, Integrated Key FOB - Supply Missing (0 - Introduction)	6 - Body and Electrical	0.1 Hrs.
Failure Code	ZZ	Service Action	

### SPARE PARTS:

Qty	Part No.	Description	Notes
1	7TB32JXWAA - MOPAR 6000634373 - EMEA	Integrated Key Fob	

## DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

## REPAIR PROCEDURE:

1. Order a second keyfob using the vehicle's VIN number.

**NOTE: Keyfob will arrive programmed and ready to use.**

2. Deliver key fob to the customer or place in the vehicle.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*