



Bulletin No.: PIT6346

Published date: 02/24/2025

Preliminary Information

PIT6346 Service High Voltage Message B2BAA

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac	LYRIQ	2024 - 2025	All All	All	All
Chevrolet	Blazer EV	2024 - 2025	All All	All	All
Chevrolet	Equinox EV	2024 - 2025	All All	All	All
Chevrolet	Silverado EV	2024 - 2025	All All	All	All
GMC	Hummer EV Pickup	2024 - 2025	All All	All	All
GMC	Hummer EV SUV	2024 - 2025	All All	All	All
GMC	Sierra EV	2024 - 2025	All All	All	All

Involved Region or Country	North America
Condition	A vehicle may be encountered with a service high voltage message. A customer may also state that at times there is no heat or cooling in the cabin. When checking for codes B2BAA will be found.
Cause	Software

Correction:

Scan vehicle for codes.

If B2BAA is found reprogram the K16 Battery Energy Control Module (BECM).

If K16 BECM programming is already up to date follow SI diagnostics for the code.

Warranty Information


Labor Operation	Description	Labor Time
2810945	Battery Energy Control Module Reprogramming with SPS	.3 Hr

Additional SI Keywords

AC, air, B2BAA, conditioning, heat, high, service, voltage

Version History

Version	1
Modified	02/24/2025 - Created on.

 GM Global Brands

© 2025 General Motors. All Rights Reserved.