



Bulletin No.: PIP5975A
Published date: 02/26/2025

Preliminary Information

PIP5975A No Movement Caused by Broken Transmission Chain

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Encore GX	2020 - 2025	All All	All	MRG
Chevrolet	Malibu	2019 - 2025	All All	All	MRG
Chevrolet	Trailblazer	2021 - 2025	All All	All	MRG

Involved Region or Country	North America
Condition	Customers may have a no movement in drive or reverse.
Cause	This may be caused by a broken transmission chain.

Correction:

Customers may bring their vehicle in with a no drive or no reverse concern.

This concern may occur with or without DTC's Setting.

The Technician should first inspect the chain per bulletin [20-NA-120](#).

If a broken chain is found, please create a TAC Case and report your findings prior to making any repairs.

Version History

Version	1
Modified	04/30/2024 - Created on. 02/24/2025 - Updated to add model year

 GM Global Brands

© 2025 General Motors. All Rights Reserved.