

DTNA Solutions > Service Solutions > Thomas Built Bus > SS 298 TBB C2 Low tone in the ICU

# SS 298 TBB C2 Low tone in the ICU

## Applicable Vehicles

C2

## Symptoms

Low tone like the oil pressure / air pressure when key on or Low air

## Issue

Several issues, could be the Low Coolant signal

The air pressure transducer module (06-96535-000). has 60 ohms resistant which it should not

## Solution

Replace the Transducer module if unit has resistant

or

Check Coolant possible sender to be replaced

Labels :

Saf-T-Liner

Add tags



0 Kudos

Comment

