



STAR ONLINE PUBLICATION



Case Number: S2513000001

Release Date: February 2025

Symptom/Vehicle Issue: Grille molding applique is sticking out at the headlamp.



Discussion: To correct a grille applique that is sticking out, the top side headlamp screws will need to be loosened. Then, partially remove the front fascia to ensure the grille molding is properly aligned and not trapped under the head light bucket. Refer to Service Library 13 - Frame and Bumpers / Bumpers / FASCIA, Front / Removal and Installation. Finally, reinstall the fascia and headlamp top screws previously loosened.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.