



WARRANTY ENHANCEMENT PROGRAM (WEP)

ID No. AB1Q0
Ref. No. QA-250219-N1
Release Date 2-24-2025

CONVENTIONAL COOLANT LEVEL SENSOR – AB1Q0

OVERVIEW

Due to an internal malfunction of the Coolant level sensor, the MIL may be illuminated or the “Low coolant level” warning light may be illuminated intermittently with a “Low coolant” message on the instrument cluster regardless of the amount of coolant.

SUBJECT VEHICLES

Certain 22MY – 23MY Conventional Trucks equipped with a Cummins B6.7 engine

WARRANTY TERMS

USE ONLY IF ABOVE CONDITIONS ARE PRESENT

- Warranty Enhancement Program: Ten (10) years and 185,000 miles from the delivery date to the initial end purchaser, or one (1) year and unlimited mileage from March 1, 2025, whichever is longer, will be covered by this program.
- For any other failure modes, standard warranty conditions will be applied.



CONVENTIONAL COOLANT LEVEL SENSOR– AB1Q0

BEFORE YOU BEGIN

- Read and understand all instructions and procedures before you begin the work.
- Read and follow all **WARNINGS** and **NOTICES** set forth in this publication. These alerts help to avoid damage to components, serious personal injury, or both.
- Park the vehicle on a flat, level and solid surface.
- Place the gear shift lever in "Neutral" or "Park".
- Apply the parking brake firmly and confirm parking brake activation.
- Turn off the engine and remove the key from the ignition switch.
- Always wear safety glasses or goggles to protect your eyes.
- Place wheel chocks in front of and behind all wheels to prevent the vehicle from moving.

PARTS

Vehicle Model Year	Part Number	Part Description	Quant. Req.
2022-2023	87469E0040	Coolant Level Sensor	1

REPAIR PROCEDURE

- Please refer to the Hino Service Manual for replacement instructions.



CONVENTIONAL COOLANT LEVEL SENSOR– AB1Q0

CLAIM APPLICATION

Reimbursable in accordance with the terms and policies of the Hino limited warranties.

COOLANT LEVEL SENSOR REPLACEMENT:

- a) Claim Type: EP
- b) Campaign No: AB1Q0
- c) Warranty code: 13221
- d) Original failed part: 9999999999
- e) Trouble code: 98
- f) Operation code: 13250AOT
- g) Labor charge: 0.8 Hr.