


UPDATE: SPEED 400 & SCRAMBLER 400 IMMOBILIZER SOFTWARE & KEY PAIRING

Last week's release of TDT 2025-03 in TOL #29956 includes a revised Speed 400 & Scrambler 400X immobilizer software intended to resolve some reported concerns with incorrect triggering of the immobilizer warning light.

This software has unfortunately reintroduced an issue affecting key pairing on these models. Should you need to pair keys on Speed 400 or Scrambler 400X, the temporary key pairing process shown in the **attached** guide must be followed.

 UPDATE Speed 400 & Scrambler 400 Immobilizer Software & Key Pairing.pdf

We continue to work on a full resolution for this concern which will be released in a later version of the TDT.