

SERVICE ACTION N961 – BLANKING CONNECTOR - INSTALL

SERVICE ACTION N961 – BLANKING CONNECTOR - INSTALL	
AFFECTED MODELS	25MY Defender
VOLUME AFFECTED	113 USA 11 CAN
REPAIR	A potential concern has been identified on certain 25MY Defender vehicles, where a junction box blanking connector is missing. A new blanking connector needs to be installed.
REPAIR TIME	0.1 hr + DIDO
CAMPAIGN LAUNCH	January 23rd, 2025
NOTES	<p>Retailers are instructed to not sell or deliver any affected vehicles under their control until the service action repair is complete.</p> <p>Sold vehicles must be repaired at the next service visit.</p>