

UNDER BONNET FUEL LINE REMOVAL AND INSTALLATION REQUIREMENT WHEN REPLACING SPARK PLUGS DURING SERVICE- NC10/NC11

Customer Voice:

- MIL on, misfire , or fuel smell after spark plug service.

Technical Description:

- Incorrect removal and/or installation of the LP fuel supply line may lead to damage to the fuel line connectors, requiring replacement.

Status:

- When replacing spark plugs, the service procedure requires the removal and installation of the LP fuel supply line (part number LR152523 or LR174145)
- Please follow the TOPIx Workshop Manual to make sure that the fuel line connectors are not damaged during removal and installation , section 310-01 Fuel Tanks and Lines - Removal and Installation - Fuel Supply Line.
- Note: If the fuel line connectors are damaged during removal or installation, the fuel line must be replaced.

Refer to SSM 76245

Range Rover

- 22MY+ Range Rover
- 23MY + Range Rover Sport

