

OIL LEAK FROM TRANSFER CASE

Customer Voice:

- Oil leak from under vehicle

Technical Description:

- Damage to the front input shaft seal and/or rear output shaft seal.

Status:

- If you have an oil leak from the front input shaft seal and/or rear output shaft seal, then do not repair the vehicle, do not clean any oil from the transfer case
- Please raise a Technical Assistance (TA) to PTS_800. Attach photos to the TA to show the transfer case oil leak
- The LTS team will work with Engineering and get you a timely repair instruction.
- Some units might be called back Via PRR.

Refer to SSM 76228

Range Rover


- 22-24MY Range Rover
- 23-24MY Range Rover Sport

Defender

- 22-24MY Defender

Discovery

- 21-24MY Discovery



E293837