

ACCESSORY FIXED SIDE-STEP BRACKET CRACKED

Customer Voice:

- The side-step makes a rattle noise.

Technical Description:

- During installation of the accessory fixed side steps (VPLRP0347 & VPLRP0530) the required spacers (kit VPLRP0487) was not installed on the front brackets as per the instructions.
- Failure to install the required spacers will lead to damage/ cracking of the front brackets.

Status:

- SSM76256 has been published to ensure that the correct spacers are installed during installation of the accessory fixed side steps.

Discovery

- 21MY -On Discovery

