

DEPLOYABLE SIDE-STEP NOISY OPERATION

Customer Voice:

- Abnormal noise coming from the deployable side-steps when deploying or retracting.

Technical Description:

- Updated TOPIx Cloud Workflows have been released under the following symptoms: Noise during operation, Erratic/ intermittent operation, Inoperative/ incorrect operation.

Status:

- Engineering is currently investigating customer concerns relating to noises from the deployable side steps.
- SSM76252** has been published to request an EPQR be submitted with details of the concern along with supporting pictures and videos, if the workflows did not resolve the concern. Please also detail actions taken to repair the noise concern.

Range Rover

- 23-25MY Range Rover
- 23-25MY RR Sport

